


Quick Guide

Steps to Update Virtual COM Driver

1. Connect the handheld scanner and the host (e.g. a PC) with a USB interface cable.
2. Enable USB virtual COM port with programming barcodes.



Start of Configuration



Enable USB virtual COM



End of Configuration

3. After the programming, the host would request driver installation. Browse your files to locate the driver and start installation. For Windows based systems:
 - Open Device Manager and select the barcode scanner you want to update
 - Select install driver from a specific location.
 - Direct the folder for .inf file.
 - Ignore the warning and continue with installation
 - A COM port is assigned to the scanner when installation is complete.
4. The USB virtual COM port is ready for use after driver installation